

SPEC DATA SHEET

Stripper Cream is a thickened multilayer paint remover. Stripper Cream can remove multiple types and layers of paint from wood and masonry. Stripper Cream can be rolled, brushed, and sprayed when diluted with water. Stripper Cream can remove heavily crusted stains from masonry substrates as well including black crust on limestone.

ADVANTAGES

- Excellent consistency and coverage that enables spray, roll, or brush application
- Ready to use right out of the container
- Pleasant odor
- Proven effective with one application
- When used properly, remains on vertical surfaces without drying out
- Product continues to work over a prolonged period of time.

LIMITATIONS

- Generally not affective on acrylics, urethanes or epoxy
- Always test first to avoid fuzzing wood.
- If product has been frozen, must remix before using.
- If product has sat for an extended period, remix before use

TECHNICAL DATA

Appearance & Odor:	Tan paste, mild odor.
Physical State:	Viscous cream
pH:	13.5
Vapor Pressure (mmHg):	N/A
Vapor Density (air=1):	N/A
Boiling Point:	212° F
Freezing/Melting Point:	N/A
Specific Gravity (water =1):	1.78
Evaporation Rate:	Extremely slow
Solubility in Water:	Complete

PREPARATION

Protect adjacent surfaces and surrounding building hardware not intended to be stripped. Avoid direct contact with foliage. Cover foliage with polyethylene or other proven protective material to capture the paint being removed.

SURFACE & AIR TEMPERATURES

Excessively high or low temperatures will produce poor results and possible harm. Best cleaning results are obtained when air and surface temperatures are above 40° Fahrenheit or less than 90° Fahrenheit. Do not clean when temperatures are below freezing or will be overnight. If freezing conditions exist, allow adequate time for surface to thaw. If air temperatures exceed 90° Fahrenheit, flash cool the surface with water before applying product. Do not allow products to dry on the surface. Always rinse thoroughly while still wet.

PRE-TESTING

Always test prior to beginning full-scale cleaning operations. Testing should confirm effectiveness on paint designated to be removed. Test also to determine the desired surface contact time and any potential for adverse reactions with adjacent materials. Allow test panels to dry thoroughly before evaluating final appearance and results.

DILUTION

Use undiluted (straight) for the best results. Dilutions may be used based on application and surface to be cleaned.

APPLICATION INSTRUCTIONS

Roll, brush, or spray through caustic compatible equipment. Apply stripper heavily to cut through multiple layers with the first application. Stripper Cream does not dry out if applied properly. Removal should begin after scrape testing in multiple areas reveals the substrate. After adequate soak time, remove the paint by scraping or by high-pressure rinse. Pressures that mark or damage the surface should be avoided.

A diluted solution of Stripper Cream (cut 4:1 with water) is recommended to reactivate the initial application. After a quick rinse, apply the diluted Stripper Cream. Rinse from the top down. The diluted product should be applied after the first pass and allowed to remain on the surface until the wall is finished. After rinsing and reapplication, do a final detailed rinse if necessary before neutralizing. When neutralizing, use NMD 80 diluted at 4 parts water to 1 part NMD 80.



EaCo Chem



**STRIPPER
CREAM**

FOR PROFESSIONAL USE ONLY

SPEC DATA SHEET

NMD80 is applied with low pressure applicator or through the EC Jet. The EC Jet automatically cuts the product to 4 parts water to 1 part NMD 80. Alkyd enamel can be removed by first applying AcrylicStrip. Allow to dwell for several minutes. While AcrylicStrip is still wet, apply Stripper Cream directly over the AcrylicStrip. After adequate soak time and a scratch test, remove the paint by scraping or by high-pressure rinse. Pressures that mark or damage the surface should be avoided.

COVERAGE RATES

Coverage rates will vary from 50 - 200 sq. ft. per gallon depending on the surface porosity, texture and severity of staining.

PRECAUTIONARY MEASURES

Precautionary Measures: Always wear goggles and chemical resistant gloves when handling this product. Keep off of skin and clothing. If material contacts clothing, wash before re-use. Do not wear contact lenses when using this product. Product is not allowed to be applied below freezing. The product contains Sodium Hydroxide and Potassium Hydroxide Do not get in eyes, on skin or clothing. Keep container closed when not in use. Applicators should wear a rain suit (plastic, rubber or PVC), boots, gloves, face shields and/or goggles to avoid contact to bare skin and eyes. Dispose of empty containers according to federal, state, and local requirements. Avoid drifting of material or rinse water onto autos and pedestrians by protecting or diverting such traffic. Do not dilute Stripper Cream with any product except water. Do not use for any other applications other than specified. Do not remove label. Read Safety Data Sheet for additional safety and health hazard information prior to use.

SPILL OR LEAK PROCEDURES

Check with the state, local, or federal regulations for waste disposal methods in the area. Wear proper protective equipment while doing cleanup. For large spills, dike and contain for intended use. For small spills, use a chemical absorbent product and place in approved container for disposal.

CONTAINER HANDLING/STORAGE

Store the product in a cool, dry place away from acids. Keep container tightly closed when not in use. Do not use pressure to empty container. Wash thoroughly after handling. Do not use container as dilution or rinsing vessel. Empty containers retain residue and must be handled as if full.

INSTRUCTIONS IN CASE OF CONTACT OR EXPOSURE

Eyes: Flood with water for 15 minutes. If irritation develops, seek medical attention.

Skin: Wash off with soap and water. Follow with a good emollient. If irritation develops, seek medical attention.

Ingestion: Drink lots of water to dilute. Do not induce vomiting. Seek immediate medical attention.

Inhalation: Move to fresh air. If irritation develops, seek medical attention.

NOTICE

This product has been classified in accordance with the hazard criteria of the CFR.

DISCLAIMER

The information herein is given in good faith, but no warranty, either expressed or implied is made. Final determination of the suitability of any material is the sole responsibility of the user. All materials may present unknown hazards and should be used with caution. Although certain hazards are described herein, we cannot be sure or guarantee these are the only hazards which exist.

CUSTOMER SERVICE

Factory personnel are available for assistance Monday through Friday from 8am to 5pm EST at (724) 656-1055. Questions can also be sent to info@eacochem.com. A reply can be expected by the following business day or FaceTime and Call from the Wall is available while on jobsite.